

# Argyle Street Asbestos Removal



WWW.PAGROUPUK.COM  
E: RECEPTION@PAGROUPUK.COM  
0845 474 0172

# CBRE



Client	CBRE
Location	167- 201 Argyle Street
Project Description	Asbestos Removal
Value	£500,000
Start / Finish Date	7th August 2017- November 2017

## Project Description

The building of 167-201 Argyle Street consists of a five-storey building, comprising of retail units and commercial offices, which were to be extensively refurbished throughout. In the first instance, we were required to carry out a refurbishment survey. Various surveys had been undertaken in the past that had highlighted numerous areas with asbestos contamination, therefore extreme care and caution was to be undertaken by the surveyor to ensure they were not at risk and additionally that any areas not currently contaminated, were not made so by the process of the surveyor.

Once all samples and the subsequent survey report had been completed, the client requested that we carry out removal works of all asbestos and contaminated items from the building, from the basement to the 5th floor.

Works were phased, with a programme of work for each stage of the project. In addition, we were required to provide enclosures to separate parts of the building from the removal works, so external cladding works could commence without interference. All works were completed on time and on budget.